# Issues

| # | Project | Tracker | Status | Severity | Subject | Assignee | Created | Updated |
|---|---------|---------|--------|----------|---------|----------|---------|---------|
| 77044 | FreeNAS | Bug | Closed | New | ACPI shutdown/reboot not working after longer uptime on HPE Microserver Gen10 | Release Council | 02/24/2019 02:27 AM | 03/21/2019 06:27 AM |